



Compatibility Guide

HP Genuine Long Life Consumables (LLCs)

Get optimal print quality and keep your printer, multifunction product (MFP), or scanner up and running smoothly with HP Genuine Long Life Consumables (LLCs). When your printer prompts you that it needs maintenance, simply pull out the kit and replace parts as needed.

Image Transfer Kit

Although your HP device's original transfer belt and drum are built to last, they wear down over time and may require replacement. An HP Image Transfer Kit has everything you need to ensure your device keeps delivering optimal print quality.

Ink/Toner Collection Kit

HP utilizes several different methods to collect unused toner, paper fibers, and dust in the imaging system. Some toner collection units (TCUs) are built into our all-in-one cartridges; others are physically incorporated into an LLC or packaged with a maintenance kit.

The TCU is an easy-to-replace, high-yield HP supply designed to reduce user-intervention rates. On many devices, the printer control panel provides a proactive alert when the TCU is approaching its end of life and you need to order a replacement.

Fuser Maintenance Kit

The fusing assembly in your HP device bonds toner to paper through a combination of heat and pressure. Replacement of your device's fusing assembly is simple with the HP Fuser Maintenance Kit.

ADF Maintenance Kit

Your HP device's ADF makes scanning and copying documents fast and simple. Stay productive and keep your ADF working properly with an HP ADF Maintenance Kit.



After installing the replacement kit in your device, easily recycle your old parts for free through the HP Planet Partners program.¹

HP Monochrome LaserJets

Printers

| Devices and LLCs | SKU number | Page yield ² |
|--------------------------------------|------------|-------------------------|
| M601/M602/M603 | | |
| Fuser Maintenance Kit 110V | CF064A | 225K |
| Fuser Maintenance Kit 220V | CF065A | 225K |
| M604/M605/M606 | | |
| Fuser Maintenance Kit 110V | F2G76A | 225K |
| Fuser Maintenance Kit 220V | F2G77A | 225K |
| M607/M608/M609/M610/M611/M612 | | |
| Fuser Maintenance Kit 110V | L0H24A | 225K |
| Fuser Maintenance Kit 220V | L0H25A | 225K |
| M712 | | |
| Fuser Maintenance Kit 110V | CF249A | 200K |
| Fuser Maintenance Kit 220V | CF254A | 200K |
| M806 | | |
| Fuser Maintenance Kit 110V | C2H67A | 200K |
| Fuser Maintenance Kit 220V | C2H57A | 200K |
| P4010 | | |
| Fuser Maintenance Kit 110V | CB388A | 225K |
| Fuser Maintenance Kit 220V | CB389A | 225K |
| P4014/P4015/P4515 | | |
| Fuser Maintenance Kit 110V | CB388A | 225K |
| 4250/4350 | | |
| Fuser Maintenance Kit 110V | CB388A | 225K |
| Fuser Maintenance Kit 220V | Q5422A | 225K |
| 9000/9040/9050 | | |
| Fuser Maintenance Kit 110V | C9152A | 350K |
| Fuser Maintenance Kit 220V | C9153A | 350K |
| 5501/5502/6500/6501 | | |
| Transfer Roller Kit | C35T5A | 225K |
| Printer Trays 2-Roller Kit | C35T6A | 150K |

MFPs

| Devices and LLCs | SKU number | Page yield ² |
|--------------------------------------|------------|-------------------------|
| M525 | | |
| ADF Maintenance Kit | L2718A#101 | 100K |
| M527 | | |
| ADF Maintenance Kit | W5U23A | 75K |
| M528 | | |
| ADF Maintenance Kit | W5U23A | 75K |
| M630 | | |
| Fuser Maintenance Kit 110V | B3M77A | 225K |
| Fuser Maintenance Kit 220V | B3M78A | 225K |
| ADF Maintenance Kit | L2718A#101 | 100K ³ |
| M631/M632/M633/M634/M635/M636 | | |
| Fuser Maintenance Kit 110V | J8J87A | 225K |
| Fuser Maintenance Kit 220V | J8J88A | 225K |
| ADF Maintenance Kit | J8J95A | 150K ³ |
| M725 | | |
| Fuser Maintenance Kit 110V | CF249A | 200K |
| Fuser Maintenance Kit 220V | CF254A | 200K |
| ADF Maintenance Kit | L2718A#101 | 100K ³ |
| M830 | | |
| Fuser Maintenance Kit 110V | C2H67A | 200K |
| Fuser Maintenance Kit 220V | C2H57A | 200K |
| ADF Maintenance Kit | C1P70A | 100K ³ |
| M4555 | | |
| Fuser Maintenance Kit 110V | CE731A | 225K |
| Fuser Maintenance Kit 220V | CE732A | 225K |
| M5025/M5035 | | |
| ADF Maintenance Kit | Q7842A | 60K |
| 9000/9040/9050/M9040/M9050 | | |
| Fuser Maintenance Kit 110V | C9152A | 350K |
| Fuser Maintenance Kit 220V | C9153A | 350K |
| 5601/5602 | | |
| Transfer Roller Kit | C35T5A | 225K |
| Printer Trays 2-Roller Kit | C35T6A | 150K |
| 6600 | | |
| Fuser Maintenance Kit 110V | C35T3A | 225K |
| Fuser Maintenance Kit 220V | C35T4A | 225K |
| Transfer Roller Kit | C35T5A | 225K |
| Printer Trays 2-Roller Kit | C35T6A | 150K |

HP Color LaserJet printers

| Devices and LLCs | SKU number | Page yield ² |
|-----------------------|------------|-------------------------|
| M551 | | |
| Fuser Kit 110V | CE484A | 150K |
| Fuser Kit 220V | CE506A | 150K |
| Toner Collection Unit | CE254A | 36K |
| M552 | | |
| Fuser Kit 110V | B5L35A | 150K |
| Fuser Kit 220V | B5L36A | 150K |
| Toner Collection Unit | B5L37A | 54K |
| M553 | | |
| Fuser Kit 110V | B5L35A | 150K |
| Fuser Kit 220V | B5L36A | 150K |
| Toner Collection Unit | B5L37A | 54K |
| M651 | | |
| Fuser Kit 110V | CE246A | 150K |
| Fuser Kit 220V | CE247A | 150K |
| Image Transfer Kit | CE249A | 150K |
| Toner Collection Unit | CE265A | 36K |
| M652/M653 | | |
| Fuser Kit 110V | P1B91A | 150K |
| Fuser Kit 220V | P1B92A | 150K |
| Image Transfer Kit | P1B93A | 150K |
| Toner Collection Unit | P1B94A | 100K |
| M750 | | |
| Fuser Kit 110V | CE977A | 150K |
| Fuser Kit 220V | CE978A | 150K |
| Image Transfer Kit | CE516A | 150K |
| Toner Collection Unit | CE980A | 150K |
| M751 | | |
| Fuser Kit 110V | 3WT87A | 150K |
| Fuser Kit 220V | 3WT88A | 150K |
| Image Transfer Kit | 3WT89A | 150K |
| Toner Collection Unit | 3WT90A | 90K |
| M855 | | |
| Fuser Kit 110V | C1N54A | 100K |
| Fuser Kit 220V | C1N58A | 100K |
| Image Transfer Kit | D7H14A | 150K |
| M856 | | |
| Fuser Kit 110V | 4YL16A | 150K |
| Fuser Kit 220V | 4YL17A | 150K |
| Image Transfer Kit | 3WT89A | 150K |
| Toner Collection Unit | 3WT90A | 90K |
| CP3520 | | |
| Fuser Kit 110V | CE484A | 150K |
| Fuser Kit 220V | CE506A | 150K |
| Toner Collection Unit | CE254A | 36K |

| Devices and LLCs | SKU number | Page yield ² |
|-------------------------|------------|-------------------------------|
| CP4005 | | |
| Fuser Kit 110V | Q7502A | 150K |
| Fuser Kit 220V | Q7503A | 150K |
| Image Transfer Kit | Q7504A | 120K |
| CP4025/CP4525 | | |
| Fuser Kit 110V | CE246A | 150K |
| Fuser Kit 220V | CE247A | 150K |
| Image Transfer Kit | CE249A | 150K |
| Toner Collection Unit | CE265A | 36K |
| 4700 | | |
| Fuser Kit 110V | Q7502A | 150K |
| Fuser Kit 220V | Q7503A | 150K |
| Image Transfer Kit | Q7504A | 120K |
| 5500 | | |
| Image Transfer Kit | C9734B | 120K |
| 5700 | | |
| Fuser Kit 110V | 527G0A | 150K |
| Fuser Kit 220V | 527G1A | 150K |
| Enhanced Fuser Kit 110V | 527G6A | 150K |
| Enhanced Fuser Kit 220V | 527G7A | 150K |
| Tray 2 Roller Kit | 527H2A | 150K |
| MP Tray Roller Kit | 527H3A | 150K |
| Image Transfer Belt | 527G8A | 150K |
| Image Transfer Belt Kit | 527G9A | 150K |
| 6700/6701 | | |
| Toner Collection Unit | 527F9A | 400k |
| Enhanced Fuser Kit 110V | 527G2A | 200k |
| Enhanced Fuser Kit 220V | 527G3A | 200k |
| Tray 2 Roller Kit | 527H2A | 150k |
| MP Tray Roller Kit | 527H3A | 150k |
| Image Transfer Belt | 527G8A | 200k |
| Image Transfer Belt Kit | 527G9A | Dependent on part. See above. |
| CP5525 | | |
| Fuser Kit 110V | CE977A | 150K |
| Fuser Kit 220V | CE978A | 150K |
| Image Transfer Kit | CE516A | 150K |
| Toner Collection Unit | CE980A | 150K |
| CP6015 | | |
| Fuser Kit 110V | CB457A | 100K |
| Fuser Kit 220V | CB458A | 100K |
| Image Transfer Kit | CB463A | 150K |
| Trays 2-Roller Kit | CB459A | 150K |

HP Color LaserJet MFPs

| Devices and LLCs | SKU number | Page yield ² |
|-----------------------|------------|-------------------------|
| M570 | | |
| Fuser Kit 110V | CE484A | 150K |
| Fuser Kit 220V | CE506A | 150K |
| Toner Collection Unit | CE254A | 36K |
| M575 | | |
| Fuser Kit 110V | CE484A | 150K |
| Fuser Kit 220V | CE506A | 150K |
| ADF Maintenance Kit | L2718A#101 | 100K ³ |
| Toner Collection Unit | CE254A | 36K |
| M577 | | |
| Fuser Kit 110V | B5L35A | 150K |
| Fuser Kit 220V | B5L36A | 150K |
| ADF Maintenance Kit | W5U23A | 75K ³ |
| Toner Collection Unit | B5L37A | 54K |
| M680 | | |
| Fuser Kit 110V | CE246A | 150K |
| Fuser Kit 220V | CE247A | 150K |
| ADF Maintenance Kit | L2718A#101 | 100K ³ |
| Image Transfer Kit | CE249A | 150K |
| Toner Collection Unit | CE265A | 36K |
| M681/M682 | | |
| Fuser Kit 110V | P1B91A | 150K |
| Fuser Kit 220V | P1B92A | 150K |
| ADF Maintenance Kit | J8J95A | 150K ³ |
| Image Transfer Kit | P1B93A | 150K |
| Toner Collection Unit | P1B94A | 100K |
| M775 | | |
| Fuser Kit 110V | CE514A | 150K |
| Fuser Kit 220V | CE515A | 150K |
| ADF Maintenance Kit | L2718A#101 | 100K ³ |
| Image Transfer Kit | CE516A | 150K |
| Toner Collection Unit | CE980A | 150K |
| M776 | | |
| Fuser Kit 110V | 4YL16A | 150K |
| Fuser Kit 220V | 4YL17A | 150K |
| Image Transfer Kit | 3WT89A | 150K |
| Toner Collection Unit | 3WT90A | 90K |
| M880 | | |
| Fuser Kit 110V | C1N54A | 100K |
| Fuser Kit 220V | C1N58A | 100K |
| ADF Maintenance Kit | C1P70A | 100K ³ |
| Image Transfer Kit | D7H14A | 150K |

| Devices and LLCs | SKU number | Page yield ² |
|--------------------------|------------|-------------------------------|
| CM3530 | | |
| Fuser Kit 110V | CE484A | 150K |
| Fuser Kit 220V | CE506A | 150K |
| Toner Collection Unit | CE254A | 36K |
| CM4540 | | |
| Fuser Kit 110V | CE246A | 150K |
| Fuser Kit 220V | CE247A | 150K |
| Image Transfer Kit | CE249A | 150K |
| Toner Collection Unit | CE265A | 36K |
| 4730/CM4730 | | |
| Fuser Kit 110V | Q7502A | 150K |
| Fuser Kit 220V | Q7503A | 150K |
| Image Transfer Kit | Q7504A | 120K |
| 5550 | | |
| Fuser Kit 110V | Q3984A | 150K |
| Image Transfer Kit | C9734B | 120K |
| 5800 | | |
| Fuser Kit 220V | 527G1A | 150K |
| Enhanced Fuser Kit 110V | 527G6A | 150K |
| Enhanced Fuser Kit 220V | 527G7A | 150K |
| Tray 2 Roller Kit | 527H2A | 150K |
| MP Tray Roller Kit | 527H3A | 150K |
| Image Transfer Belt | 527G8A | 150K |
| ADF Maintenance Kit | 6H121A | 75K |
| Image Transfer Belt Kit | 527G9A | 150K |
| 6800/6801 | | |
| Toner Collection Unit | 527F9A | 400k |
| 110V Enhanced Fuser Kit | 527G2A | 200K |
| 220V Enhanced Fuser Kit | 527G3A | 200K |
| Tray 2 Roller Kit | 527H2A | 150K |
| MP Tray Roller Kit | 527H3A | 150K |
| Image Transfer Belt | 527G8A | 200K |
| ADF Maintenance Kit | 6H122A | 150K |
| ADF Flow Maintenance Kit | 6M1P3A | 300K |
| Image Transfer Belt Kit | 527G9A | Dependent on part. See above. |
| CM6030/CM6040 | | |
| Fuser Kit 110V | CB457A | 100K |
| Fuser Kit 220V | CB458A | 100K |
| ADF Maintenance Kit | CE487C | 60K |
| Image Transfer Kit | CB463A | 150K |
| Trays 2-Roller Kit | CB459A | 150K |

HP scanners and OfficeJet X printers and MFPs

HP Scanners

| Devices and LLCs | SKU number | Page yield |
|------------------------------------|------------|-------------------|
| 2500 f1 | | |
| ADF Roller Replacement Kit | L2748A#101 | 30K ³ |
| 2500 f1 | | |
| A Roller Unit | 4T8E4A | 100K |
| A Pad Unit | 4T8E6A | 30K |
| 3500 f1/4500 fn1 | | |
| ADF Roller Replacement Kit | L2742A#101 | 100K ³ |
| 3600 f1 | | |
| A Roller Unit | 4T8E4A | 100K |
| A Pad Unit | 4T8E6A | 30K |
| N4600 fnw1 | | |
| B Roller Unit | 618J9A | 100K |
| A Separation Unit | 4T8E5A | 100K |
| N6600 fnw1 | | |
| A Roller Unit | 4T8E4A | 100K |
| A Separation Unit | 4T8E5A | 100K |
| N9120 fn2 | | |
| ADF Roller Replacement Kit | J8J95A | 150K ³ |
| 2000 s1 | | |
| ADF Roller Replacement Kit | L2760A#101 | 100K ³ |
| 3000 s3 | | |
| ADF Roller Replacement Kit | L2754A#101 | 100K ³ |
| 2000 s2/3000 s4/N4000 snw1 | | |
| ADF Roller Replacement Kit | 7QH79A#101 | 100K ³ |
| 5000 s4/5000 s5/7000 s3/N7000 snw1 | | |
| ADF Roller Replacement Kit | L2756A#101 | 100K ³ |
| 7500/Digital Sender 8500 fn1 | | |
| ADF Roller Replacement Kit | L2718A#101 | 100K ³ |
| Digital Sender 8500 fn2 | | |
| ADF Roller Replacement Kit | J8J95A | 150K ³ |
| 4200 | | |
| ADF Roller Replacement Kit | 9Y0H9A | 180K |
| 9000 flw | | |
| ADF Roller Replacement Kit | 9Y0J0A | 200K |

OfficeJet X Printers and MFPs

| Devices and LLCs | SKU number | Page yield ² |
|---------------------|------------|-------------------------|
| X476 | | |
| Ink Collection Unit | B5L09A | 115K |
| X477 | | |
| Ink Collection Unit | B5L09A | 115K |
| X555 | | |
| Ink Collection Unit | B5L09A | 115K |
| X585 | | |
| Ink Collection Unit | B5L09A | 115K |



HP PageWide printers and MFPs

PageWide Printers

| Devices and LLCs | SKU number | Page yield ² |
|-------------------------|------------|-------------------------|
| 556 | | |
| Ink Collection Unit | B5L09A | 115K |
| 750/755/765 | | |
| Service Fluid Container | W1B44A | 150K |
| Printhead Wiper Kit | W1B43A | 150K |
| Trays 2-x Roller Kit | W1B45A | 150K |

PageWide MFPs

| Devices and LLCs | SKU number | Page yield ² |
|-----------------------------|------------|-------------------------|
| 586 | | |
| Ink Collection Unit | B5L09A | 115K |
| ADF Maintenance Kit | W5U23A | 75K |
| 772/777 | | |
| ADF Maintenance Kit | W1B47A | 50K |
| Service Fluid Container | W1B44A | 150K |
| Printhead Wiper Kit | W1B43A | 150K |
| Trays 2-x Roller Kit | W1B45A | 150K |
| 774/779 | | |
| Heated Pressure Roller 110V | 3MM39A | 450K |
| Heated Pressure Roller 220V | 3MZ76A | 450K |
| ADF Maintenance Kit | W1B47A | 50K ³ |
| Service Fluid Container | W1B44A | 150K |
| Printhead Wiper Kit | W1B43A | 150K |
| Trays 2-x Roller Kit | W1B45A | 150K |
| 780 | | |
| ADF Maintenance Kit | J8J95A | 150K |
| Service Fluid Container | W1B44A | 150K |
| Printhead Wiper Kit | W1B43A | 150K |
| Trays 2-x Roller Kit | W1B45A | 150K |
| 785/785+ | | |
| Heated Pressure Roller 110V | 3MM39A | 450K |
| Heated Pressure Roller 220V | 3MZ76A | 450K |
| ADF Maintenance Kit | J8J95A | 150K |
| Service Fluid Container | W1B44A | 150K |
| Printhead Wiper Kit | W1B43A | 150K |
| Trays 2-x Roller Kit | W1B45A | 150K |

1. HP Planet Partners program: Program availability varies. For more information, visit hp.com/recycle.

2. Stated yield is based on 5% coverage and may vary based on coverage and media type used, media size, short edge feed on A3 devices, and job size.

3. Scans through ADF.

© Copyright 2026 HP Development Company, L.P. The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

